

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Wednesday, January 16, 2013

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:  
Matthew Haak  
START-USEPA  
Situation Unit Leader



1. Source Area, observed a crew collecting soil cores.



2. Source Area, observed a crew collecting soil cores.





3. Frac Tank City, no decon operations observed.



4. Ceresco Dam impoundment observed ice.





5. Ceresco Dam impoundment, observed bank ice forming.



6. MP10.4 & MP10.5 Sediment Traps observed the sediment traps frozen over.





7. MP10.75 Sediment Trap ice conditions.



8. MP11.78 Sediment Trap ice conditions.





9. MP14.75 Sediment Trap ice conditions.



10. South Mill Pond and North Mill Pond observed ice forming.





11. MP19.15 LDB observed an RI crew.



12. MP19.25 Sediment Trap ice conditions.





13. MP21.5 Sediment Trap ice conditions.



14. MP26.0 Sediment Trap ice conditions.





**15. MP28.25 Sediment Trap ice conditions.**



**16. MP30.8 Sediment Trap ice conditions.**





**17. MP33.0 A Sediment Trap ice conditions.**



**18. MP33.0 B Sediment Trap ice conditions.**





**19. Morrow Lake Delta observed ice forming.**



**20. Morrow Lake Delta observed ice forming.**





**21. Morrow Lake Delta/Morrow Lake Neck observed ice forming.**



**22. Morrow Lake Delta/Morrow Lake Neck observed ice forming.**





**23. Morrow Lake observed the lake frozen over.**



**24. Morrow Lake observed the lake frozen over.**